

# Manhole Inspection Summary

Manhole # S17UU\_009MH

Printed On: 6/10/2009

Page 1 of 3

**Inspection** ☒ **Is Incomplete** Rating:

Record Plat: **17UU** Node: **009** Status: **Not Found**

Insp Date: **3/5/09 9:45 AM**

Incomplete Comments

**Cannot Access - Require Cleaning - Manhole Existing  
Confirmed by As-Built Drawing**

Crew: **ads4**  
Inspector: **ADS2**  
Firm: **ADS**

**Location** Address: **REAR OF 3120 REISTERSTOWN RD** Cross Street: **CHOWAN AVE**

**Manhole** Type: Location: Ground Conditions: **Dry**  
☐ Prev. Rehab Weather: **Dry** Subject To Ponding: **None**

Comments **MEASURED 105 FEET FROM UPSTREAM NODE AND 76 FEET FROM SUPPOSED  
LOCATION OF DOWNSTREAM NODE. SEARCHED IN LARGE AREA WITH METAL  
DETECTOR - REGARDLESS OF EXISTING CONCRETE BLOCK AND MISCELLANEOUS  
OTHER DEBRIS, METAL DETECTOR DID NOT FIND ANY METALIC OBJECTS**

**Cover** Shape: Diameter: (in.) Length: (in.) Dist A/B Grade: (in.)  
Type: **Sanitary** Condition: Cover Material: **Cast Iron**  
Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

**Frame** Offset: (in.) Condition: ☐ Sound ☐ Cracked ☐ Leaks

**Chimney / Frame Adjustment** ☐ Exists Material: ☐ Parged Height: (in.)  
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated  
Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Corbel** Material: ☐ Parged Type:  
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated  
Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Barrel** Material: ☐ Parged  
Shape: Diameter: (in.) Length: (in.)  
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated  
Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Bench** ☐ Exists Material: ☐ Parged  
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

**Channel** Material: ☐ Parged  
Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:  
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

**Steps** Count: Missing: ☐ Corroded

**Surcharge** ☐ Evidence Of Surcharge Depth: (ft.) ☐ Active Surcharge Present

# Manhole Inspection Summary

Manhole # S17UU\_009MH

Printed On: 6/10/2009

Page 2 of 3

Location View



DEBRIS AROUND WHERE MH SHOULD BE



WATER BEING DUMPED INTO AREA WHERE MH SHOULD BE



